

Working Draft Workshop Planning

Working Session: Quality Assurance Plan

Session Focus:

Identify the details that need to be addressed in the quality assurance plan for PCB samples that are collected under the comprehensive monitoring plan.

Session Specifics:

What method(s) will be required, and for what purpose(s)?

What project specific requirements will be specified where a method provides options or recommendations?

How will laboratory blank contamination be evaluated with respect to data acceptance?

When will transfer (trip) blanks and rinsate (equipment) blanks be necessary and how will they be evaluated with respect to data acceptance?

What instructions or requirements need to be provided to potential contract accredited laboratories and what information is needed to qualify them?

Session Presenters:

Session Duration: